

Message

From: Brent Weber [bweber@iterm.com]
Sent: 6/5/2019 4:26:05 PM
To: Adams, Adam [Adams.Adam@epa.gov]; kelly.cook@tceq.texas.gov; Kendra Bernhagen (Kendra.Bernhagen@Tceq.Texas.Gov) [Kendra.Bernhagen@Tceq.Texas.Gov]; spill12 [spill12@tceq.texas.gov]; Moore, Gary [Moore.Gary@epa.gov]
Subject: Updated Update
Attachments: Tank Levels and Tank Update 6-5-19.xlsx

I updated the information around Incident Water remaining in tank 80-34, assuming 1.5 turnovers of the tank would be needed to remove the incident related material.

Per that theoretical calculation, around 10,000 bbls of incident related water remains in tank 80-34.

Brent J. Weber
Intercontinental Terminals Company LLC
Senior Vice President, Sales and Marketing
Office: 281-884-0277
Cell: 225-806-5136
Bweber@iterm.com